
Subject: Icom IC-2720 Repair
Posted by [root](#) on Sat, 02 Jan 2016 02:31:18 GMT
[View Forum Message](#) <> [Reply to Message](#)

The ICOM IC-2720 decided to quit and stop transmitting in the middle of a QSO. I pulled the radio apart and to my surprise, a bad pin diode.

All cleaned up:

Back together with the new pin diode: